


# Winfield Hydraulic Cylinder Replacement

Waylon Humphrey, PE

LRL-Maintenance Section

Project Engineer



US Army Corps of Engineers  
**BUILDING STRONG**®



# Presentation Outline


- Background Info & Purpose of the Repair
- Known Challenges
- Repair Process
- Future plans (Olmsted)
- Questions/Comments




---

**BUILDING STRONG®**

# Location of Winfield L&D




# Location of Winfield L&D



**BUILDING STRONG®**

# Winfield Locks and Dam

- Began Operation in 1935 as 6 Roller Gates and two 360' Lock Chambers
- Hydroelectric Power Plant added around 1984
- 800' chamber and Tainter Gate added in 1997




**BUILDING STRONG®**

# Layout of Winfield L&D




**BUILDING STRONG®**

# Background Information



**BUILDING STRONG®**

# Background Information



**BUILDING STRONG®**

# Background Information



- Cylinders remain extended the majority of the year.
- Cylinders were installed with ceramic coated rods



**BUILDING STRONG®**

# Why Ceramic?

- Cost
- Position Sensing System
- Promoted as Superior to other coatings



---

**BUILDING STRONG®**

# Cylinder Details

- ~34,000lbs
- ~39ft Long (retracted)
- 31ft Stroke
- 20.47" Bore Diameter
- 6.66" Rod Diameter
- \$735,000.00 (replacement)



# Background Information



Flood Conditions 2003

- Cylinders rotate about trunnion as they retract.
- Never fully retract



**BUILDING STRONG®**

# Purpose of Replacement

- New Lock Chamber/Tainter Gate were commissioned in 1997
- By 2005 ceramic coating was visibly failing



May 2005



**BUILDING STRONG®**

# Purpose of Replacement

- Failed ceramic coating prevented raising of gate for fear of damaging seals.



2008



2013



**BUILDING STRONG®**

# Failure of Ceramic Coating

- Corrosion was caused by water penetration through the porous ceramic coating
- Water penetration occurred after the rod lost its coating of hydraulic oil due to never being retracted
- Contributing factors were sunlight and maybe natural bending of the rod
- The rods are not salvageable



# Replacement Cylinders

- Chrome Plated Stainless Steel Rods
- Ordered by LRH – on site at Winfield




**BUILDING STRONG®**

# Known Challenges


- Cylinders were installed in the dry via cofferdam and hydraulic crawler crane below tainter gate
- No access on upstream side of gate
- Work access platform for rod/ gate connection
- Removing connection pins/ installing new pins
- Cylinders must be lifted in/ out through trunnion mount
  - Two crane lift, with primary crane using both hoists.
- Support for new cylinder rod as it extends to connection point
- Tolerances on new pins and spherical bushings



# Original Installation (1997)



- Use of Main and Aux hoists to control angle
- Rigged around cylinder body just below trunnion
- Rod Support mounted to pier



**BUILDING STRONG®**

# Original Installation (1997)




- Unable to sit pins into journals due to interference of rigging with framing
- A second crane was used to finish the lift




**BUILDING STRONG®**

# No Upstream Access





**BUILDING STRONG®**

# Work Access to Pin Connection



**BUILDING STRONG®**

# Removing Connecting Pins



- Largest Clearance  
 Bearing 7.8755" & Pin 7.8745" = +.001"

- Smallest Clearance  
 Bearing 7.8737" & Pin 7.8756" = -.002"

Gate Ear Design 7.876"+.002 vs. Actual 7.872"



**BUILDING STRONG®**

# Condensed Repair Process

- Construct safe work access to rod/gate connection, secure cylinders, lifting lugs added to cylinders
- Attempt to push/pull pin
- Cut and remove cylinder rod
- Cut rod eye away from pin
- Cut and remove pin
- Remove old cylinders
- Construct support for extending new cylinder rod
- Install new cylinder/extent rod/make connection to gate
- Repeat for 2<sup>nd</sup> cylinder



# Repair Process



Left: Placing 100T mobile crane

Right: Man basket access



**BUILDING STRONG®**

# Repair Process



- Fabricated pad eyes to secure cylinder and rod
- Added lifting lugs



**BUILDING STRONG®**

# Repair Process

- Failed to remove pin using hydraulic rams.
- Proceeded to remove cylinder rod to allow for removing rod eye from pin.



**BUILDING STRONG®**

# Repair Process

- With rod removed, the rod eye was cut from the pin and area prepped for new pin




**BUILDING STRONG®**

# Repair Process



# Repair Process



# Repair Process



**BUILDING STRONG®**

# Repair Process

- With cylinder removed a support ramp was fabricated to support the rod as it extended



# Repair Process

- Installation of new cylinder with same technique as removal



**BUILDING STRONG®**

# Repair Process

- The same process was then performed on the opposite cylinder
- Once both cylinders were hooked up and ready the rods were extended down the support beam.



# Repair Process


- New pins were installed by freezing them in liquid nitrogen, and making sure all component diameters were at the end range of tolerance.



**BUILDING STRONG®**

# Repair Process

- Rod support ramp then had to be removed from under cylinder



# New Cylinder Installed



- Tested cylinders as much as High Pool would allow
- Scheduled Duration 30 Days
- Actual Duration 21 Days
- Allowed for Additional Work on Roller Gate




**BUILDING STRONG®**

# Future Plans

- A very similar direct connect design is being implemented at Olmsted Lock and Dam.
  - Normal low pool will have pin connection submerged
  - Cylinders would have to be replaced with bulkheads set and tainter gate in top position (limiting clearance around cardan ring)
  - Multiple gates in a row removes ability to use lock walls for mobile crane
  - Addition of lifting lugs to trunnion casting
  - Method of removal without multiple cranes? (lifting beam/eliminate need to lower through cardan ring & support framing)
  - Tolerance of pin connection: Will the cylinder rods and rod eye have to be scrapped any time a cylinder is replaced?



# Work on Roller Gate



# Questions



**BUILDING STRONG®**