

STILLING BASIN DEWATERING BOX

Ross Woodbury
Project Engineer
Louisville District
February 9, 2010



US Army Corps of Engineers
BUILDING STRONG




Stilling Basin Problems

- Damage to concrete surface
- Damage to baffle blocks
- Damage to embedded gate sill
- Damage due to barge accidents
- Debris in stilling basin
- Problems are Division/Corps wide with no way to repair the complete basin




BUILDING STRONG

Side View




BUILDING STRONG®

Side View




BUILDING STRONG®

Top view



BUILDING STRONG®

Transport Barge



BUILDING STRONG®

Cost/Delivery

- PRIP asset
- Money requested for 2011 construction
- MDC to administer construction contract
- Delivery estimated for 2012 delivery



BUILDING STRONG®